

APPLICATION OF WARNING FLAG WITH RED TOOL (1024)

STEP 1.



PULL ON THE RINGS
UNTIL THE CLAMP STAYS OPEN.
ATTACH TOOL TO A HOTSTICK

TOP VIEW AFTER STEP 3.



SHOWS RINGS HOOKED OVER
PEG

STEP 2 & 3.



PUT THE CLAMP RING OVER THE PEG ON
LEFT CUP OF TOOL. **2**
SWING THE SPRING LOADED RIGHT CUP
TO THE LEFT & PUT CLAMP INTO CUP.
RELEASE CUP SO CLAMP IS HELD IN
TOOL. **3**

STEP 4.



POSITION THE CLAMP UP
UNDERNEATH THE CONDUCTOR
AND PUSH UP QUICKLY
CAUSING IT TO SNAP SHUT

REMOVAL OF FLAGS



TO REMOVE : PUT HOOK
THRU ONE OF THE FINGER
RINGS ON SNAP CLAMP AND
PULL DOWN UNTIL IT OPENS
THEN LIFT UP TO IT SLIDES
ONTO THE HOOK TOOL OR
FALLS TO THE GROUND

HOTSTICK



**Do not attach the clamp
sideways on the conductor.
The flag should be hanging
vertically straight down
from the wire as shown
above.**



MOB 0274865549
PH 09 9506290

ENERGY EQUIPMENT LTD.
PO BOX 56229 AUCKLAND 1446

www.ene.co.nz sales@energyequipment.co.nz